



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Susumu EGUCHI, et al.

Application No.: 10/773,153

ATTENTION

Confirmation No.: 5459

CERTIFICATE OF CORRECTION

Filed: February 9, 2004

BRANCH

U.S. Patent No.: 7,132,921

Issued: November 7, 2006

For: P

POWER SUPPLY MODULE AND ELECTRONIC APPARATUS USING THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

į

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date:

David M Pitcher

Registration No. 25,908

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500

Facsimile: (202) 434-1501

Certificate

JAN 1:0 2007

of Correction

JAN 1 6 2007

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,132,921

DATED: November 7, 2006

INVENTOR(S): Susumu EGUCHI, et al.

Column 9, Line 47, after "transformer" change "," to --;--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 7,132,921

No. of add'l copies @ 50¢ per page